


Site location & photographs



Site location & access plan



Green algae from the seawall steps to be removed



Damaged sealants to be replaced



Damaged Navigation marker to be repaired